

**RESOLUTION NO. 1747  
Telecom Surplus**


**A Resolution of the Board of Commissioners of Public Utility District No. 1  
of Okanogan County Declaring Certain Equipment Surplus and  
Authorizing the Sale or Disposal Thereof.**


WHEREAS, from time to time, the District has equipment that is either obsolete or no longer needed; and

WHEREAS, the District has determined the equipment listed in Exhibit A attached hereto is surplus to the District's needs;


NOW, THEREFORE, BE IT RESOLVED that the Board of Commissioners of Public Utility District No. 1 of Okanogan County now declares as surplus the items described in Exhibit A. The Board authorizes the sale or disposal thereof in a manner that is determined by staff to be in the District's best interests.

PASSED AND APPROVED April 12, 2021.

  
Jerry Asmussen, President

  
William C. Colyar, Vice President

ATTEST:

  
Scott Vejraska, Secretary

APPROVED as to form:

  
Heidi E. Appel, General Counsel

Resolution 1747 - Exhibit A

Qty	Manufacturer	Device Type	Reason/Notes												
1	Fujikura	40S Fusion Splicer S/N 3128	Replaced with a newer model												
2	Ciena	3902 Service Delivery Switches	Failed in field												
1	Lightening Edge	LE310 Aggregation Switch	Obsolete												
6	Motorola	MC 2 pole 12' power cable, P/N 30009315002	Obsolete												
4	Motorola/Zebra	7181 APs	Replaced with Cambium <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 50%;"></th> <th style="text-align: center;">MAC</th> </tr> <tr> <th style="text-align: left;">Serial Number</th> <th style="text-align: left;">Address</th> </tr> </thead> <tbody> <tr> <td>683imu0019</td> <td>5c0e8b16e7b0</td> </tr> <tr> <td>683ims0091</td> <td>5c0e8b16e07c</td> </tr> <tr> <td>683ims0076</td> <td>5c0e8b159324</td> </tr> <tr> <td>683imu0032</td> <td>5c0e8b16e8ec</td> </tr> </tbody> </table>		MAC	Serial Number	Address	683imu0019	5c0e8b16e7b0	683ims0091	5c0e8b16e07c	683ims0076	5c0e8b159324	683imu0032	5c0e8b16e8ec
	MAC														
Serial Number	Address														
683imu0019	5c0e8b16e7b0														
683ims0091	5c0e8b16e07c														
683ims0076	5c0e8b159324														
683imu0032	5c0e8b16e8ec														
4	Cambium	450 5ghz uncapped SM, P/N C054045C004B	Replaced with 450B												
28	Cambium	450 5ghz 20m cap SM, P/N C054045C003B	Replaced with 450B												
2	Cambium	450D 5ghz 20m cap SM, P/N C054045C013B	Replaced with 450HG												
31	Cambium	Cassegrain Lens (CLIP) Antenna	Replaced with 450B/HG												
8	Ubiquiti	Nanobeam 19 5ghz SM	Obsolete												
8	Ubiquiti	Nanobridge M5 5ghz SM	Obsolete												
10	Ubiquiti	Nanobridge M2 2ghz SM	Obsolete												
40	Ubiquiti	Powerbeam 400 5ghz SM	Obsolete												
4	Ubiquiti	Nanostation M2 2ghz SM	Obsolete												
16	Ubiquiti	Nanostation M5 5ghz SM	Obsolete												
3	Cambium	29V CMM AP Power	No longer needed												
3	CPI	Trio-16F Radio Phone	Obsolete												
8	Sino-American	PSU for Trio-16F Phones	Obsolete												